

Date: Tues	sday, 09/10/2007 2:55:12 PM			
	a Lacelle	Process Sheet	Split-	-(4) -//
Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: ARM	
Job Number	: 35030 - 2_			
Estimate Number	: 12882		ADTENDICTORY (CENT	
P.O. Number	:NIA	Part Number	: D3560042	
This Issue	: b9/10/2007 S.O. No. : NA	Drawing Number	: D3560 REV C	
Prsht Rev.	: NC : SMALL /MED FAB	Project Number	: N/A	
First Issue	: MT Type : SMALL /MED FAB : 35030		14: 14:	(4)
Previous Run	. 55050	Material Due Date	: 19/10/2007 Qty:	Um: Each
Written By	15 1-1-1-	Due Date	. torioizoor day.	Jo om.
Checked & Approv		50		
Comment	: Est Rev: A New Issue 07.05.24 est rev B ECN 987 07.10.09	EC verified by: DD		
111111111111111111111111111111111111111		LC Verified by, DD		
Additional Produc	t			
Job Number:				
Seq. #:	Machine Or Operation:	Description:		
1.0	M6061T6B0500X05000	6061-T6 Bar .50" x 5.0"	(1881)(1881)(1881)	
Comm	nent: Qty.: 1.4648 f(s)/Unit Total: 14.647	'5 f(s)		
	6061-T6 Bar 0.50" x 5.00"	10		
	Batch: Secret		56- czue -V	(4)
2.0	BAND SAW	BAND SAW		
Comm	ent: BAND SAW			
	Cut blanks 16.750" long		FC 67.10 38	(.5)
3.0	HAAS1	HAAS CNC VERTICAL MACHININ		
Comm	ent: HAAS CNC VERTICAL MACHINING #1			
	1- Mill as per Folio FA694 Rev: & D	wg D3560 Rev:	"	
	2-C'sink 0.196" hole on manual mill as per	dwg D3560		
	W.			
	3-Deburr per dwg D3560		BK 7.12	. 28 (10)
4.0	QC2	INSPECT PARTS AS THEY COME	OFF MACHINE	
	ent: INSPECT PARTS AS THEY COME OFF M		BC- 07.10	28 (10)
5.0	QC8	SECOND CHECK		
0	COND OUTSU			1/10/29
Comm	ent: SECOND CHECK		2.1 0	7/10/21




Tuesday, 09/10/2007 2:55:12 PM Date: Linda I acelle User: **Process Sheet** Drawing Name: ARM Customer: CU-DAR001 Dart Helicopters Services Part Number: D3560042 Job Number: 35030 Job Number: Description: Seq. #: Machine Or Operation: PLATE 6.0 D35921 Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s) 17.11.08 PLATE 7.0 LARGE FAB LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 STEP: 1- clean material (buff bracket and bottom of arm with blue pad) 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5- set up machine to 135 amps 6- weld across bottom and top ends 7- reheat with torch (8- on one side weld from bottom to top half way 9- same for other side (half way) 10- from half way point weld the rest of the first side (ease off pedal near end) 11- same for remaining side (ease off pedal near end) INSPECT WORK TO CURRENT STEP 8.0 QC5 Comment: INSPECT WORK TO CURRENT STEP VISUAL WELDING INSPECTION QC9 9.0 Comment: VISUAL WELDING INSPECTION 7-11-08 HAND FINISHING RESOURCE #1 HAND FINISHING1 10.0 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1



Tuesday, 09/10/2007 2:55:12 PM Date: **Process Sheet** User: Linda Lacelle Drawing Name: ARM Customer: CU-DAR001 Dart Helicopters Services Part Number: D3560042 Job Number: 35030 Job Number: Description: Seq. #: Machine Or Operation: INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 11.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION Spacer D2808 12.0 10.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qty.: 35 330 Spacer SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 13.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 07-11-15 1-Press bushing in D3560 arm per dwg D3562 INSPECT WORK TO CURRENT STEP 14.0 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 15.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: FINAL INSPECTION/W/O RELEASE 16.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE 4 89.11.15 Job Completion

Page 3

Form: rprocess



DART AEROSPACE LTD	Work Order:	35030
Description: Arm	Part Number:	D3560-2
Inspection Dwg: D3560 Rev: 8		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	5065	/			
Ø0.196	+0.005/-0.001	196	_			
Ø1.000	+0.010/-0.001	1-0-5				
0.500	+/-0.010	(0) 5				
0.250	+/-0.010	25+752				
0.275	+/-0.010	.277				
0.188	+/-0.010	181				
2.000	+/-0.010	2.001				
1.700	+/-0.010	1.721				
Ø0.385 x 100°	+/-0.010 x 0.5°	350				
0.250 Deep	+/-0.010	. 257				

Measured by:	7	Audited by:	3.1	Prototype Approval:	N/A
Date:	2-10 28	Date:	07/m/21	Date:	N/A
	7-10 20				

Í	Rev	Date	Change	Revised by	Approved
			New Issue P/o D3560 - 042	KJ/JLM LA	
3			Dimensions updated per Dwg Rev B	KJ/JLM KJ/JLM	E
	В	07.00.13	Differisions aparted per Birg its.	10	



D3560-1 ARM (-041, SHOWN)
OR D3560-2 ARM (-042, OPPOSITE)

D3592-1 PLATE,
SEE DETAIL A

D3560-041 ARM WELDMENT (SHOWN), D3560-042 ARM WELDMENT (OPPOSITE)

> PLATE (REF)

- ARM (REF)

DETAIL A (SCALE 1:1) D3560-3 ARM (-043, SHOWN)
OR D3560-4 ARM (-044, OPPOSITE)

D3592-1 PLATE,
SEE DETAIL A

D3560-043 ARM WELDMENT (SHOWN), D3560-044 ARM WELDMENT (OPPOSITE)

GENERAL NOTES

- 1) WELD PER QSI 004
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES



	СВ		07.06.19	REMOVE POWDE	R COAT
	A		06.09.25	NEW ISSUE	TELDMENT, ADD FOCKETS
COPYRIGHT @ 2006 BY DART AEROSPACE LTD.	DESIGN	9	DRAWN BY	DART	DART AEROSPACE LTD.
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE	CHECKE	*	APPROVED #	DRAWING NO. D3560	REV. SHEET 1 OF
OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	07.06	.19	13	ARM WELDMENT	sca

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 350050

1.557

